





Middle landing between 2<sup>nd</sup> & 3<sup>rd</sup> floor:  
Water and mold damage




3<sup>rd</sup> floor top landing:  
Plaster, water damage and mold.





3rd floor Hallway:  
Ceiling tile, water damage and mold.



3<sup>rd</sup> floor Bucket